

Dear Roxanna Witter and Crew:

Thank you for all your time and effort. This is very comprehensive, and I didn't read every part thoroughly, but I did skim over all of the other parts.

I do have a few comments to make about the parts that I did read through:

1. Under 1, point 5.1.4, (I think) the Fig. 1 map is missing. Either include it here, or have a link to the one at the end.
2. Under Noise, 3.4, it seems counterproductive to make a recommendation and then say, "If industrial haul routes are NOT developed..." Leave that part out, since your recommendation is for them to develop these routes.
3. Under Community Wellness, 3.5, a Community Advisory Board sounds good, but it could be a real problem if a cross-section of the community isn't represented. Right now the BMSA board appears to be pro-drilling, and therefore Antero would have no overseeing of its practices, etc.
4. Under Accidents and Malfunctions, require that Antero takes the FIRST responsibility for all problems and that they deal with their subcontractors later, not making the ones affected stuck with one company blaming the other. In other words, no "passing the buck."
5. Under Recommendations, #9 "As a condition of SUP—skip "when available." They MUST do it or not be approved to drill.
6. Why are 10 storage tanks allowed??? There should be NO deep injection of wastewater WITHIN the PUD! Arkansas just suspended drilling due to many earthquakes from wastewater being injected into the ground. Denver had earthquakes about 50 years ago after they had been putting wastewater into deep dry wells at Rocky Mt. Arsenal!

As a suggestion to your staff, re-read carefully for missed words, misused words, and typos.

Also, it would be much easier to read this if the final copy had all the pages numbered consecutively, instead of within headings, and listed as such in the table of contents. It's very difficult to scroll to the spot the way it's set up now.

Under Comments, at the end the sideways charts are mind-numbing and neck-breaking to read. Is there some way to orient them horizontally?

Thanks again. I hope that Antero and BMesa CO take notice. Their SUP agreement never should have been approved. The original map of Exxon well pads was not shown, mentioned, or given to 90% of the land and/or homebuyers in Battlement Mesa. Having seen that map after the 2009 announcement of Antero's plan to drill in B. Mesa, that map only allowed one well per pad, not up to 20 as currently planned. We homeowners are being held hostage to their power and greed.

Sincerely,

Sandra Getter